

**Mohali branch Address:**
**NIPRO MEDICAL INDIA PVT.LTD, khatan No 761/786, Chandigarh  
 Zirakpur Road, Village Bhaghat Zirakpur, Mohali, Punjab Phone :- 18002095200**
**INSTALLATION/SERVICE REPORT** **Report No: 197**

 Hospital Name : Civil Hospital  
 Address : Jugdhari (DCC)  
 Nephrologist:  
 Chief Technician:  
 Biomedical Engineer:

 Model : 55 Aus  
 Serial No : 18x11576, 18x10432, 26, -27, -11977  
 Nature of Call : BO  
 AMC/CAMC/Warranty/On call :  
 Installation date : 09/02/2019  
 Warranty Expiry date : 2/02/24  
 Hour Meter Reading : 9323, 7174, 10415, 1576, 708/14

 Errorcode: Concl. mod taking of Bi-carbonate  
 Machine Software Ver : Coupler Switch

Type :

 Action Taken 18x11576 & Portform Concl. Calibration.  
18x10432, -26, -27, V21 valve lowest  
side thin pipe found kinked, Pump doing jerking.  
Kindly donot pull the A & B-Part line  
during cleaning process.

Parts to be Used/Replaced:	Material code	Description:	Qty :
<u>18x11977</u>	<u>Found</u>	<u>Coupler Plug Switch</u>	<u>1000</u>
<u>Again line</u>	<u>that</u>	<u>is in proper way</u>	

 Call status completed Yes  No 

 Comments (Service Engineer): Now all m/c's working properly.  
Kindly do disinfection timely and properly.  
Use transducer protection for correct venous chamber to m/c.

Comments (Unit-In-charge):

 Signature of Service Engineer: Havinder K. Seal & Signature of Customer  
 Date: 15/07/22 Time:  Date:  Time: 


- Please follow standard disinfection protocol as recommended.
  - AAMI standard RO water should be provided to Hemodialysis machines.
  - It's mandatory to run the machine only with servo stabilizer or UPS.
  - If spare part damaged due to power fluctuation while not using UPS or servo stabilizer are not covered under warranty/CAMC.
- Physical damage, misplaced and missing spare parts are not covered under warranty/CAMC.