



# NIPRO MEDICAL INDIA PVT. LTD

CUSTOMER COPY

Mohali Branch Address:

NIPRO MEDICAL INDIA PVT LTD, Khatan No 761/766, Chandigarh

Zirakpur Road, Village Bhaghat Zirakpur, Mohali, Punjab Phone :- 18002095200

## INSTALLATION/SERVICE REPORT

Report No: **3058**

Hospital Name: Civil Hospital  
 Address: Kaithal (Depe)  
 Nephrologist:  
 Chief Technician:  
 Biomedical Engineer:

Model: Serdial 50 Plus  
 Serial No: 19CX13948, 19CX13946, 19CX14143  
 Nature of Call: BO  
 AMC/CAMC/Warranty/On call:  
 Installation date: 23/06/2017  
 Warranty Expiry date: 22/06/2018  
 Hour Meter Reading:

Errorcode: Blood Pump bearing, CLV position Error

Machine Software Ver: Type:

Action Taken: 19CX13948 -> Change 4 pieces bearing of both roller of Blood Pump.  
19CX13946 -> change 4 pieces bearing of both roller of Blood Pump and change microlimit switch of CLV.  
19CX14143 -> change 2 pieces of bearing of blood Pump roller and microlimit switch of CLV.

Parts to be Used/Replaced:	Material code	Description:	Qty:
----------------------------	---------------	--------------	------

<u>19CX13941 -&gt;</u>		<u>change microlimit switch of CLV.</u>	
------------------------	--	---	--

status completed Yes  No

Comments (Service Engineer): Now all these ml's working properly

Comments (Unit-In-charge):

Signature of Service Engineer: Ravinder K. Seal & Signature of Customer: [Signature]  
 Date: 10/09/24 Time: Date: [Signature] Time:



- Please follow standard disinfection protocol as recommended.
- AAMI standard RO water should be provided to Hemodialysis machines.
- It's mandatory to run the machine only with servo stabilizer or UPS.
- If spare part damaged due to power fluctuation while not using UPS or servo stabilizer are not covered under warranty/CAMC.
- Physical damage, misplaced and missing spare parts are not covered under warranty/CAMC.

micro Switch. = 300  
19C x 13946

micro Switch = 300  
19C x 13941

micro Switch = 300

19C x 14143

900

---

two Bearing → = 300

19C x 14143

4 Bearing → = 600

19C x 13946

4 Bearing. → = 600

19C x 13948

1500



# Transaction Successful

14:22 pm on 10 Sep 2024

## Paid to



RAVINDER KUMAR

₹2,400

8053902710

Banking Name : RAVINDER KUMAR



Payment Details



Transaction ID

T2409101422096450876881



Debited from



XXXXXX3442

₹2,400

UTR: 462066339198



Date

25th Jan


DCDC



19CX13941



DCDC/CHKTL/HDMAC/002



DLG

19CX13946



DCDC/CHKTL/HDMA 1106







**19cx14143**







**19cx14143**



**Bearing change working**

**19cx14143**



**19cx14143**



**19cx13946**  
**Bearing 2**

A close-up photograph of a person's hand holding a small, cylindrical metal component. The component has a threaded outer surface and a central hole. A white label with the text '19cx13946' is placed below the component. The background is a blue surface, possibly a workbench or a container, with some blurred tools and a white cloth visible.

**19cx13946**



**19cx13946**



**19cx13946**



**Switch change**

**19cx13946**



A close-up photograph of a person's hand holding five disassembled metal components of a bearing. The components are arranged on the palm: a ball bearing on the left, a small ring in the center, a larger ring on the right, and another ball bearing at the bottom. A white rectangular label with the text '19cx13948' is positioned at the bottom of the hand. The background is a blue surface with some blurred objects.

**19cx13948**



**19cx13948**



**19cx13948**



**4 new bearings good  
working  
19cx13946**