



**NIPRO**  
Your Partner in Health Care

CUSTOMER COPY

**NIPRO MEDICAL (INDIA) PVT. LTD.**

Unit No.-306, III Floor, Time Tower, M.G. Road, Gurgaon - 122 002, HARYANA  
Tel. : +91 124 4278 601 / 4378 601 Toll Free No.: 1800 209 5200

**INSTALLATION / SERVICE REPORT**

DATE 19/03/17

Report No.

<b>HOSPITAL DETAILS</b>		<b>MACHINE DETAILS</b>	
Hospital Name : <u>Civil Hospital</u> Address : <u>Sinsa (DCDC)</u>		Model : <u>Surdial 55+</u>	Serial No :
Nephrologist : Chief Technician : <u>Mr. G. M. Rana</u> Bio Medical Engg.		Nature of Call : AMC/Warranty/ on call	1. <u>16CX 5837</u> 2. <u>88</u>
Problem Reported Date :                      Time :		Installation Date : <u>19/8/17</u>	3. <u>39</u>
Err Code : <u>Installation</u>		Warranty Expiry Date : <u>18/03/22</u>	4. <u>40</u>
Problem Observed		Hour Meter Reading :	5. <u>41</u>
Date :		6. <u>42</u>	
Time :		Err Code : <u>Installation</u>	7. <u>43</u>
			8. <u>84</u>
Action Taken <u>Installation</u> → <u>Install all 8 Surdial 55 Plus machines successfully. Cond. → 14.0 Temp. → 37°C</u> <u>m/c's are ready for treatment. All m/c's are working properly due to rinse &amp; dialysis.</u>			
Parts used :	Article No. :	Description :	Qty : Price :
Parts to be Replaced :	Article No. :	Description :	Qty : Price :
Call Status - Completed		Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
Comments (Service Engineer) : <u>Machines are install successfully. But install without sensor &amp; stabilizer, as per discuss with Mr. Pandita Sir, Responsibility of Installation of</u>			
Comments (Unit-in-Charge) : <u>machine without sensor (stabilizer) is taken by Mr. Shahnoaz &amp; Mr. Akshat CEO. If there is any fault into m/c due to power fluctuation company not responsible for this.</u>			
Signature & Name of Service Engineer Date : <u>19/03/17</u> Time :		Signature of the Nephrologist / Unit-in-charge Date : <u>19/03/17</u> Time :	

